

## RISK MANAGEMENT REMOTE ASSESSMENT

Report Prepared For: Sample Hotel

Property Address: 20 Bedrooms, Richmond, Surrey, UK,

Postcode: TW1 6UV

Email Address: sample-report@riskstop.co.uk

Date of Survey: 02/03/2021

RiskSTOP Survey No: 54585481

Risk Consultant: David Reynolds

Broker: Marsh

Underwriter: Property Investors


For Queries Please Contact: Survey-Enquiries@riskstop.co.uk

The Risk Management Report must be read in conjunction with the Instructions and Basis of Consultation Report detailed later in this report.





Front Elevation Rear Elevation











SUMMARY OF BUSINESS ACTIVITIES (a brief overview of the Company – how long established, length of time at this site, part of larger business, overview of the occupation and of any trade processes, including any risk management features in place to mitigate those processes)

The property has operated as a hotel for 40 years, originally built and used as a residential dwelling.

The site comprises a 20 bedroomed hotel with all rooms being en-suite. There is a dining room and a small commercial kitchen which includes a mixture of gas and electrically powered equipment. There is no deep fat frying equipment.

The hotel has a self-service laundry room with two washing machines and two tumble dryers. The lint traps are checked and cleared on a daily basis by housekeeping staff.

The kitchen and laundry equipment are maintained under contract.

Reception is manned 24/7.

## PROPERTY DETAILS

Main Building Material:	Brick and render
Roof Type and Material:	Slate, hipped roof
Number of Floors (excluding basement):	Three
Basement Yes / No:	Yes
Year of Build (if listed):	Early 18 <sup>th</sup> Century
Residential / Commercial / Usage:	Commercial – Hotel
Extension / Conservatory:	N/A
Outbuildings Structure / Usage:	N/A
Other Permanent Structures:	Walling and paving
Car Parking / Loading Bays etc:	Car parking is available at the front of the property

#### ADDITIONAL COMMENTS

N/A



# **TOP RELEVANT RISKS BY RISK CLASS** (Additional comments to be provided where findings are anything other than 'Normal')

1. Hot Work Permit / Co	ntrol of Contractors	Unfavourable
Additional Comments:	Basic contractor controls are in place with the the responsibility for them.	on-site maintenance man having
	Currently no hot work permit – rir refers.	
2. Electrical Testing		Normal
Additional Comments:	IET wiring inspection every 5 years, last under	taken 2019 with satisfactory rating.
	PA testing annually with housekeeping staff c their daily duties.	hecking bedroom items as part of
3. Health and Safety Pol	icy	Normal
Additional Comments:	Health & safety policy in place and considered the business.	d relevant for size and complexity o
4. Fire Risk Assessment		Favourable
Additional Comments:	Fire risk assessment undertaken annually by a January 2021. No actions raised.	external contractor, last completed
5. Risk Assessments		Normal
Additional Comments:	Example risk assessments provided and cons undertaken across the hotel.	idered to reflect the tasks
6. Cooking Equipment (N	Maintenance / Duct / Extraction / Cleaning)	Favourable
Additional Comments:	Kitchen equipment maintained under contract ductwork is cleaned throughout its length by Filters are cleaned by the maintenance man o	contractors also on an annual basis.
7. Health and Safety Tra	ining	Normal
Additional Comments:	Suitable health and safety training is given to held. Staff sign to acknowledge their underst	
8. Housekeeping		Favourable
Additional Comments:	Housekeeping staff are on site on a daily basis throughout.	s and will clean and tidy the building
9. Slips Trips and Falls		Normal
Additional Comments:	Some carpeted areas, but staff are tasked wit carpeting or floors are damaged.	h reporting any areas where
10. Electrical Portable A	ppliance Testing	Favourable
Additional Comments:	PA testing annually with housekeeping staff c their daily duties	hecking bedroom items as part of
11. Tumble dryers		Favourable
Additional Comments:	There are two tumble dryers within the laundinguests. Housekeeping staff check and clean check sheet provided within the room.	



## **ACTION FOR UNDERWRITERS**

## **Policy Conditions complied with?**

YES

Additional Comments:

Portable heaters in the form of plug electrical heaters are available for guests which is not in compliance with the portable heater exclusion on the policy. The heaters are checked as part of the overall PA Test and are checked before each use. It is suggested that this form of heating is accepted, and that the endorsement is amended to reflect this.

Risk Improvement Report raised?

YES

**Additional Information?** 

NO

Comments:

## **LOCATION INFORMATION & PHOTOGRAPHS**

### **Fire Station**

Nearest whole time brigade is based in Richmond within 3km of the premises, with an approximate attendance time of 8 minutes. The whole-time brigade is part of London Fire Brigade. No issues are anticipated with access to the premises.

## **Flooding Information**

Flood Zone 1 - Land and property in flood zone 1 have a low probability of flooding







Google Aerial View





#### **IMPORTANT NOTICE**

This risk management report (**Report**) is confidential and has been prepared by RiskSTOP Limited (**RiskSTOP**) for the benefit of the client (and its group companies) (together the **Client**) in relation to a property or site which is the subject of this Report solely for the purpose of providing either risk control advice or information in connection with the binding or writing of insurance or reinsurance where it is also being underwritten by the Client (**Permitted Purpose**). In addition, this Report (or part thereof) may be disclosed by the Client to the policyholder or its broker, but neither shall be entitled to rely upon it.

This Report may not be copied or disclosed to any other person in whole or in part or used for any other purpose without the prior written consent of RiskSTOP.

This Report is based solely upon information provided by the policyholder. The information for the Report is gathered securely by way of telephone surveys and does not include a physical survey or inspection of the property or site to which the Report relates and neither RiskSTOP nor its employees, agents or sub-contractors will visit the property or site in person for the purposes of carrying out the assessment.

The Client should acknowledge that a physical site survey or inspection of the property may produce differing results than the result of a telephone survey is able to produce.

Save for the warranty that the Report has been prepared using reasonable skill and care, all warranties, conditions, and other terms implied by statute or common law are excluded to the fullest extent permitted by law. Without prejudice to the foregoing, the maximum aggregate liability of RiskSTOP (and its group companies) and its employees, agents and sub-contractors for any liability and losses of whatever kind and howsoever arising (including negligence), as a result of access to, use of, or reliance upon, any information contained in this Report is limited to £5,000,000 (five million pounds). Neither RiskSTOP nor its group companies nor their respective employees, agents or sub-contractors shall be liable to any person for indirect, consequential, or special losses. In no circumstances shall RiskSTOP, its group companies or their respective employees, agents or sub-contractors be liable to any person other than the Client or where the Report has not been used for the Permitted Purpose.

Nothing in this disclaimer shall limit or exclude the liability of RiskSTOP to the extent such liability cannot be lawfully limited or excluded.